

# WAX RECOMMENDATION



## Fort Kent Frostbite 40K

10<sup>th</sup> Mountain Ski Club, Fort Kent, ME

Sunday, January 10

Noon

22K/40K Skate

Mass start

3 loops

Forecast/Conditions: Saturday night low -7F, Sunday cloudy with a high about 10F. Snow temperature at start 2F to 5F. Forecast is cold weather Wednesday through Saturday. Should be a hard packed powder surface.

Glidewax: Apply LF Moly/LF Blue mixed 1:1, scrape and brush, then apply HF Blue, sprinkle on Nordlite Powder X-cold, iron in together, scrape and brush. Finish by rotocorking JetStream Blue, brush with a dedicated nylon polishing brush and polish with a thermopad.

Structure: A fine linear grind covered by one pass with the Blue TOKO Structurite tool (old fine-linear wheel) before JetStream application will best suit these conditions.

Racing - Service

Check the WaxTip page at [www.TokoUS.com](http://www.TokoUS.com) before all of your races for the latest waxing information. The Toko Race Wax Tips offer racers precise waxing advice on how to make your skis perform optimally for a given event. For racers who don't have top end waxes, skip the Fluorocarbon (JetStream) and substitute the LF or System 3 wax of the same color (Yellow, Red or Blue). For those who do not have a rotocork for applying JetStream, the next best thing is to iron it in.