

# WAX RECOMMENDATION



## Leadville Loppet

Leadville, CO

Saturday February 23

10AM Start

22K or 44K Freestyle

Forecast/Conditions: Low 5F. High 28 degrees F. Chance of snow= 50%

Glidewax: Apply LF Moly/LF Blue, mixed 1:1, scrape and brush, then apply HF Blue, scrape and brush out well. Finish by rotocorking JetStream Moly, and polishing with a nylon brush, and polishing with a thermopad.

Gripwax: Roughen base with 120 grit sandpaper, and iron in TOKO Base Green. Cover with 2-3 layers of TOKO Carbon Blue.

Structure: A fine structure will best suit these conditions.

Racing - Service

---

Check the Waxtip page at [www.TokoUS.com](http://www.TokoUS.com) before all of your races for the latest waxing information.

The Toko Race Wax Tips offer racers precise waxing advice on how to make your skis perform optimally for a given event. For racers who don't have top end waxes available, skip the Fluorocarbon (HelIX, JetStream) and substitute the LF or System 3 wax of the same color (Yellow, Red, Blue). Additionally, for those who do not have a rotocork (for applying JetStream), this step can be replaced by vigorously corking with a dedicated Plasto Cork as the expense of durability.