

# WAX RECOMMENDATION **TOKO**<sup>®</sup>

## **Craftsbury Marathon**

Craftsbury, VT

Saturday, January 31

9 A.M. all racers, 9:05 A.M. all tourers

25K/50K Classic, mass start, self-seeded

1 or 2 loops

Forecast/Conditions: Friday night low temp 7F with 50 percent chance of snow. Saturday high of 20, with 30 percent chance of flurries. Snow temp will be in teens most of the race. Expect wind. A snowstorm is underway with approx accumulation of 10-16" in NEVT, followed by slight additional accumulation Friday; Choose soft skis if you have them. Tracks will be beautiful!

Glidewax: Iron on LF Blue/LF Moly mixed 1:1, scrape and brush. Then apply HF Blue, sprinkle on Nordlite Powder X-cold, iron in together, scrape and brush out well. Rotocork JetStream Blue, brush with a dedicated nylon polishing brush and buff with a thermopad.

Gripwax: Roughen base with 150 grit sandpaper, iron in Carbon BaseWax Green, cork smooth, let cool. Then apply 2-3 layers of Carbon GripWax White, corking between layers. Check with Toko Tech Team at start area or pasta feed wax clinic Friday evening for updates.

Structure: Choose your cold grind skis. Or add fine linear structure, created by one pass with the fine-linear wheel of a Toko structurite tool (before JetStream application).

Check the WaxTip page at [www.TokoUS.com](http://www.TokoUS.com) before all of your races for the latest waxing information. The Toko Race Wax Tips offer racers precise waxing advice on how to make your skis perform optimally for a given event. For racers who don't have top end waxes available, skip the Fluorocarbon (JetStream) and substitute the LF or System 3 wax of the same color (Yellow, Red or Blue). For those who do not have a rotocork for applying JetStream, the next best thing is to iron it in.

**Racing - Service**