

WAX RECOMMENDATION



World Masters Championships

Ponderosa State Park, McCall, ID

Sunday, 2 March

10-30k Skate start times from 9am

Forecast/Conditions: Low overnight 19F (-5C), high of 32F (0C) Sunday. Probable light snow showers. Expect fast hard packed trails.

Glidewax: Apply LF Moly, scrape and brush. Apply HF Moly (if no HF Moly, apply HF Red), scrape and brush. Apply JetStream High Speed (if bloc, rotocork or if powder, iron). Then brush out with nylon polishing brush and polish with Thermo Pad. Apply a very light spray of HelX Warm in a warm room and let dry completely. Then polish with Thermo Pad.

Gripwax: N/A

Structure: Using the Toko Structurite, a Coarse Linear structure should be applied twice before applying the JetStream High Speed. Otherwise a universal stonegrind.

Racing - Service

Check the Waxtip page at www.TokoUS.com before all of your races for the latest waxing information. The Toko Race Wax Tips offer racers precise waxing advice on how to make your skis perform optimally for a given event. For racers who don't have top end waxes available, skip the Fluorocarbon (HelX, JetStream) and substitute the LF or System 3 wax of the same color (Yellow, Red, Blue). Additionally, for those who do not have a rotocork (for applying JetStream), this step can be replaced by vigorously corking with a dedicated Plasto Cork as the expense of durability.